



Re-attach non-energized leads	Shock	Secured area, area warning signs, working hot permit, PPE (safety glasses)	Y	1	2	1	2	4								
Re-attach energized leads	Shock	Secured area, area warning signs, working hot permit, PPE (safety glasses)	Y	1	2	2	3	12								
Further Description of Controls Added to Reduce Risk:																
*Risk:	0 to 20		21 to 40			41-60			61 to 80			81 or greater				
	Negligible		Acceptable			Moderate			Substantial			Intolerable				