procedure for switching on PS

1) set points to zero (live current), leave On's blank
2) live current → Go, check at bottom left corner
3) watch Wm column go to zero
4) Stable to On individually

6.15 Cryo needs tunnel access to clear lead flow problems
Holed ½ h off for 2f work



← Horizontal

$$\frac{\Delta p}{p} = \frac{.735\, f_{3dB}}{n f_0 \eta}$$

$$= \frac{.735 \cdot 8496}{2.069 \times 10^9 \cdot -.007}$$

$$\frac{\Delta p}{p} = 4 \times 10^{-4} \text{ RMS}$$

← Vertical

Chromaticity appears well corrected