

WCM near end of store, showing
hop ~~to~~, two buckets
synchrotron satellites disappeared from
Schottky spectrum after hop.

2:20 am Quench link interlock.
3:40 AM PS tech coming in for node card problem.

0615: Magnets back, after 1 hysteresis cycle. Horiz orbit bad - >5 mm. on 1st turn.
Trying another hysteresis cycle first (up to γ=30), since injection correction look
ok from Wolfram's app.
0700: 2nd time around is no better (see following page)