

20.35 switching magnet

20:40 test of Yellow radial loop. ramp radially 3mm with and without loop, should be a small difference of ~5% according to T. Hayes seems to be ok

20:45 ramp again, same problem in Yellow