

times when the beams started to get lost.



Y_H

B_H

$Q_H = 0.2512$

$Q_H = 0.2037$



Y_V

B_V

$Q_V = 0.1979$

$Q_V = 0.218$

raised the Q_H in blue by 0.005

both re-coolers were emptied. So, we had to refill this store.