



REV A 8/25/95
REV B 6/6/96 ECN AG00203
FRMERFF CHANGED IN SERFRMDC.TDF FROM
DFF TO SRFF. GLITCHES WERE OCCURRING
ON FRMERFF.pn DURING STATE CHANGES.
THIS WAS NOT EVIDENT FROM SIMULATION FILES.

SERIAL LINK PS REG BOARD					
COMPANY	brookhaven lab				
DESIGNER	Kurt Vetter				
SIZE	EV	NUMBER	1.00	REV	B
DATE	1:19p 9-24-1997				SHEET 1 OF 1