

19:00 Water leak in AGS. Leak was going on since 3pm but now the situation became critical. → AGS stops.

19:30 Beam is still stored in RATIC. After the chromaticity measurement we want to see a difference orbit
 → tweak b07-th6, then activate a ramp in Blue
 beam drops at injection!

We learn the hard way that to do a tweak we should either

- * use "here2last" in WFG manager
- * create a new ramp from store 12

21:50 Beam back into the Ring at injection.

Measured Q_x : 0.114

Q_y : 0.143

Ramp to 60 starts at 22:06.

Beam lost at transition → radial jump did not get triggered.

